



Errata

NFPA 30A

Code for Motor Fuel Dispensing Facilities and Repair Garages

2008 Edition

Reference: 4.2.4, 4.3.2.7(5) and 4.3.2.8

Errata No.: 30A-08-1

The Committee on Automotive and Marine Service Stations notes the following errors in the 2008 edition of NFPA 30A, *Code for Motor Fuel Dispensing Facilities and Repair Garages*.

1. *Revise 4.2.4 to read as follows:*

4.2.4 Where tanks are at an elevation that produces a gravity head on the dispensing device, the tank outlet shall be equipped with a device, such as a normally closed solenoid valve, positioned adjacent to and downstream from the valve specified in ~~4.3.2.5.1~~ 22.13.1 of NFPA 30, *Flammable and Combustible Liquids Code*, that is installed and adjusted so that liquid cannot

2. *Revise 4.3.2.7(5) to read as follows:*

(5) The tank storage complies with Chapter ~~2~~ 22 of NFPA 30, *Flammable and Combustible Liquids Code*.

3. *Revise 4.3.2.8 to read as follows:*

4.3.2.8 Aboveground tanks shall be provided with spill control that meets the requirements of ~~4.3.2.3~~ 21.7.1 of NFPA 30, *Flammable and Combustible Liquids Code*. Tank fill connections shall be provided with a noncombustible spill containment device.

Issue Date: March 13, 2008

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/codelist)