



HAUNTED CASTLE AMUSEMENT FACILITY FIRE

Jackson Township, NJ

May 11, 1984



**FIRE
INVESTIGATIONS**

NATIONAL FIRE PROTECTION ASSOCIATION

1 Batterymarch Park, PO Box 9101, Quincy, MA 02269-9101 USA
Telephone: 1-617-984-7263 E-mail: investigations@nfpa.org

Investigation Report

Haunted Castle Amusement Facility Fire
Jackson Township, New Jersey
May 11, 1984

Prepared by

John Bouchard
Assistant Division Director
Engineering Services Division
National Fire Protection Association

In Cooperation with

Federal Emergency Management Agency/
United States Fire Administration

and

National Bureau Standards/
Center for Fire Research

This investigation was conducted by the National Fire Protection Association (NFPA) under an agreement with the Federal Emergency Management Agency/United States Fire Administration (FEMA/USFA) and the National Bureau of Standards/Center for Fire Research (NBS/CFR). The investigation was jointly funded by these agencies and the NFPA.

The substance of this investigation report is dedicated to the public. It may be freely reprinted with customary crediting of the source. The author and publisher are solely responsible for the accuracy of the statements or interpretations contained herein.

ABSTRACT

In the early evening hours on May 11, 1984, a rapidly spreading fire destroyed the "Haunted Castle" amusement facility at the 200-acre Six Flags Great Adventure Park located in Jackson Township, New Jersey, approximately 50 miles south of New York City. At the time of the fire, there were an estimated 28-34 visitors and three employees in the Haunted Castle. Eight of the visitors, unable to immediately exit the structure died in the fire.

The one-story structure was comprised of 17 commercial trailers with approximate dimensions of 8 feet high by 8 feet wide and 40 feet long. The trailers were connected together by means of plywood and wood framing. The front facade of the structure consisted of a wall approximately 35 feet high by 109 feet long with three smaller portions that projected into the Park area.

The interior of the Haunted Castle was constructed of plywood partitions which created a convoluted path of travel approximately 450 feet in length. Materials used for the interior of the Haunted Castle included synthetic foam, various fabrics and plastics, plywood, and tar paper.

There were a total of seven exits, including the main entrance. Fire protection features included emergency lighting and portable fire extinguishers. There was no automatic detection or automatic sprinkler protection provided in the facility.

County fire investigators determined the cause of the fire to be the accidental ignition of a wall mounted, polyurethane foam pad by a cigarette lighter.

The following are considered to be major factors contributing to the loss of life in this fire:

- The failure to detect and extinguish the fire in its incipient stage by means of fixed fire detection and suppression systems.
- The ignition of synthetic foam material, and subsequent fire and smoke spread involving combustible interior finishes and contents.
- The difficulty of escape by occupants due to fire conditions in the haunted house type of environment.

Table of Contents

	<u>Page</u>
I. Introduction	1
II. Background	3
III. The Incident	8
IV. Analysis	11
V. Appendices	18
A. Figures 1 and 2	
B. Photographs	

I. INTRODUCTION

The National Fire Protection Association (NFPA), with assistance from the Building Officials and Code Administrators International, Inc. (BOCA), investigated the "Haunted Castle" amusement facility fire at the Six Flags Great Adventure Park in Jackson Township, New Jersey in order to document and analyze significant factors that resulted in the rapid spread of the fire and loss of life.

This study was conducted under a major fires investigation agreement between the Federal Emergency Management Agency/United States Fire Administration (FEMA/USFA), the National Bureau of Standards/Center for Fire Research (NBS/CFR), and the NFPA. The agreement; funded by FEMA/USFA, NBS/CFR, and the NFPA, provides for the investigation of technically significant fires by the NFPA's Fire Investigations and Applied Research Division to document and analyze incident details and report lessons learned for life safety and loss prevention purposes.

The NFPA was assisted in the data collection and analysis efforts by the Building Officials and Code Administrators International, Inc. (BOCA) under an agreement between the NFPA and three model building code organizations, to investigate significant building fires throughout the United States. In addition to BOCA, the other cooperating building code groups are the International Conference of Building Code Officials (ICBO) and the Southern Building Code Congress International, Inc. (SBCCI). The three model building code groups are supporting NFPA by lending technical staff support for on-site field work and building code analysis.

The NFPA became aware of the Haunted Castle amusement facility fire on the night it occurred. John Bouchard, Assistant Division Director of Engineering Services; and William D. Dupler, Staff Engineer, Building Officials and Code

Administrators International; traveled to the Six Flags Great Adventure Park in Jackson Township, New Jersey to document the facts related to the fire.* A 2-day on-site study and subsequent analysis of the incident are the basis of this report. Data collection activities were made possible by the cooperation of the Ocean County Fire Marshal's office.

This report is another of NFPA's studies of fires having particular educational or technical interest. The information presented is based on the best data available during the on-site data collection phase and further data acquired through subsequent follow-up. It is not the NFPA's intention that this report pass judgment on, or fix liability for, the loss of life in the Haunted Castle amusement facility. This report describes fire protection conditions at the Haunted Castle amusement facility and presents findings on factors contributing to the rapid spread of the fire and loss of life based on NFPA's analysis of the collected data and observations during the investigation. The cooperation and assistance of John Garcia, Ocean County Fire Marshal, is greatly appreciated.

A special thanks to is extended Mr. William D. Dupler, Staff Engineer, Building Officials and Code Administrators International, for his on-site assistance in the data collection phase and for his input into the code analysis.

*Mr. Dupler has since left the employ of BOCA.

II. BACKGROUND

The Six Flags Great Adventure Park is located on a 200-acre site in Jackson Township, New Jersey, approximately 50 miles south of New York City. The Park offers visitors a wide variety of amusement rides, shows, and special entertainment events. During 1983, more than 3.3 million people visited Great Adventure Park.

In the Fall of 1978, a Haunted Castle facility consisting of four trailers, was located at the Park for several weeks. The attraction proved to be popular and a larger 17-trailer Haunted Castle facility was erected at the Great Adventure Park in early 1979. In 1980, the facility was air conditioned and in 1981, the interior of the Haunted Castle was refurbished. Since the Haunted Castle opening in 1978, approximately 7.4 million visitors had ventured through it.

The Haunted Castle facility was a single-story structure comprised of 17 used, commercial trailers of various manufacture and a wood frame facade. Fifteen were box trailers, and two were open flatbed trailers. The trailers had been fabricated using either steel or aluminum bodies, with wood floors and 1/4-inch plywood riveted to the interior of the trailer frame. Each box trailer had approximate dimensions of 8 feet high by 8 feet wide and 40 feet long. The two flatbed trailers were approximately 35 feet in length. The trailers were arranged in a symmetrical fashion forming two rectangular sections. The spacing between the trailers varied from as little as a few inches to as much as 2 1/2 feet (See Figure 1 and Photo 2).

The trailer portion of the building was divided into two identical 8-trailer (mirror image) sections, each of which constituted a complete and separate Haunted Castle. One or both of the sections could be in operation,

depending on crowd size. The 17th trailer served as the control room where employees prepared costumes and make-up prior to participating as haunted house characters. The control room contained electrical panels for both mirror image sections of the Haunted Castle as well as tables and chairs, lockers, a telephone, and two pressurized water fire extinguishers.

The trailers were connected together by means of plywood and wood framing. The interiors of the trailers were designed to simulate the atmosphere of a Haunted Castle through the use of a darkened, convoluted series of passageways that were intended to disorient and scare visitors for amusement purposes as they progressed through the facility.

A facade providing a castle-like appearance was built in front of the trailers and contained the main entrances and exits for each of the two sections. The facade was composed of a wall approximately 109 feet long and 35 feet high with three attached smaller structures that projected into the Park area. The total area of the facade was approximately 1,128 square feet. The facade was built of unprotected wood frame construction. Walls were constructed using wood studs placed 16 inches on center, covered with plywood and composite sheathing board, while the roof was formed using pre-fabricated wood trusses. In the main exiting areas of the facade, studs that formed the interior walls were exposed. These areas provided space for displays and included a wooden ramp. The front of the facade had an exterior finish comprised of sprayed and painted urethane foam. In some areas, wire mesh with 55-gallon drums were arranged in various shapes and sprayed to achieve the desired effect. The rear of the facade was constructed of 1/2-inch plywood with a tar paper covering to provide weather resistance.

General interior construction in the trailer portions of the facility included plywood and wood stud partitions and ceilings of plywood on wood structural members suspended below the trailer roofs. Other available construction details are noted below.

Upon entering the darkened, convoluted passageways, a visitor would first encounter a rat lady, a butcher, and then a coffin display (See Figures 1 and 2). The butcher display was designed to be manned by an employee who entered the display through a passageway connected to the control room. The interior walls of the display area consisted of 2-inch by 3-inch wood studs on which 1/2-inch plywood sheets, painted black, had been nailed. Some of the displays were protected from visitor damage by plexiglass windows, metal grates, and bars.

Continuing further through the Haunted Castle, a visitor would encounter a phantom of the opera display and then a corridor with strobe-lights. Wood partitions in this area were constructed of 2-inch by 3-inch wood studs covered by 1/4-inch plywood. The ceiling in this area was also finished with 1/4-inch plywood. Synthetic foam, (identified during the investigation by Ocean County authorities as polyurethane) was installed on the walls to provide bumper protection for visitors traveling through the strobe-light corridor.* An emergency exit door was located at the beginning of the strobe-light corridor approximately 226 feet from the entrance. The door was equipped with panic hardware and marked with a lighted exit sign adjacent to the exit.

The next area encountered was the spider room and the second emergency exit which was located approximately 336 feet from the main entrance. This exit door was also equipped with panic hardware and marked with a lighted exit sign located adjacent to the exit. The interior of the spider room consisted of loosely applied tar paper and fabric from which spider-like webs were

*Exact dimensions of the foam bumper could not be obtained during the investigation as the material was consumed. The estimated overall dimensions were 3 1/2 feet wide by 5 feet high based on burn pattern observation.

hung. In that area were two human-like figures constructed of papier-mache' and an assortment of various sized rubber spiders. Special effects were achieved with low wattage color lights and small motors that moved the webs and spiders.

Visitors would then enter a tunnel, cave-like passage. This passage was constructed using 2-inch by 3-inch wood stud partitions which were arranged in rough shapes and heights. Tar paper was stapled to the partitions and wire mesh was applied over it. A plaster mix was applied over the wire mesh and painted.

The final area encountered was different, in that it was built on a flatbed trailer. A fiberglass barrel, approximately 7 feet in diameter and 20 feet in length, was mounted on the flatbed trailer. The barrel was supported from the bottom by tires that were inflated and mounted on rims. One wheel, driven by an electric motor, provided rotation of the barrel using a gear/chain arrangement. This flatbed trailer was covered by a wood frame structure. After passing through this area, visitors traveled a short distance and left the Haunted Castle through a main exit at the front.

In addition to the exit facilities described above, fire protection provisions included emergency lighting arranged to illuminate interior passageways in the event of power failure (due to the extent of damage, further details were not determined by NFPA). There were no detection and alarm systems or automatic sprinklers installed in the facility.

Great Adventure Fire Brigade

Great Adventure Park maintains a fire brigade that operates a 750 GPM pumper equipped with a 750-gallon booster tank. Two men are assigned to each shift and additional manpower and equipment are provided through a formal mutual aid plan with Jackson Township. Public fire protection in Jackson Township is provided by four volunteer fire companies.

Water Supply

The Great Adventure Park has its own water system maintained by the Jackson Municipal Utilities Authority. A one-million gallon storage tank located at ground level, supplies water to the Park's underground water mains and fire hydrants. Water for the ground level storage tank is supplied by pumps from artesian wells. Investigators were unable to collect any detailed data on the water supply system, however, fire ground officers indicated that water supply was not a problem.

III. THE INCIDENT

On Friday, May 11, 1984, an average crowd of approximately 15,000 visitors was at the Great Adventure Amusement Park. One of the two mirror-image sections (right hand, "Red" side - See Figure 1.) of the Haunted Castle was open to the public, and four employees were on duty.

There was a line of visitors waiting to travel through the Haunted Castle, and employees were allowing approximately 10 visitors to enter per minute. At the time of the fire it was estimated that there were about 30 visitors in the facility, based on an estimated travel time through this attraction of approximately 3 minutes. At approximately 6:30 p.m., an employee positioned at the butcher display smelled smoke. The employee went to investigate the odor of smoke and entered the passageway which connected the butcher station to the phantom of the opera station. As the employee traveled through the passageway, he observed heavy smoke coming from the phantom area and then proceeded back through the butcher station to the main gate to alert the other employees and instruct them to discontinue entry of visitors. He then re-entered, went to the control room and notified the Great Adventure Fire Brigade by telephone. He then left the Haunted Castle via the control room door. Looking to his right, he saw smoke and flames around the emergency exit door located at the strobe room. Meanwhile, an adult visitor traveling through the darkened passageways discovered the fire, ran through the remainder of the castle and alerted an employee.

Specific details of visitor evacuation were not determined; however, individuals and groups of visitors apparently used the main entrance, the main exit and both rear exits. One visitor was rescued from the coffin area by an employee (also see IV. Analysis).

Fire Brigade Operations

The Great Adventure Fire Department received telephone notification of the fire in the Haunted Castle at 6:35 p.m.. While enroute to the scene, the captain, observing a heavy smoke condition, instructed security to notify the Jackson Township Police Department and implement the mutual aid plan.

Upon arrival, the captain advanced a 1 1/2-inch handline through the front entrance of the Haunted Castle. He was able to advance approximately 20 feet into the building to where heavy fire conditions were encountered that forced his withdrawal. The captain then attacked the fire from the rear of the trailers and later assisted mutual aid fire department units.

Mutual Aid Fire Departments

The Jackson Township Police Department received telephone notification of the fire at 6:41 p.m., and two of the four Jackson Township volunteer fire companies were dispatched. The first mutual aid company was located approximately four miles from the Park and arrived on the scene approximately 11 minutes after receiving the alarm. The second mutual aid company, located approximately 15 miles from the Park, arrived on the scene at 6:56 p.m. These units were directed to enter through the employee gate and set up behind the castle.

The initial mutual aid fire department units to arrive also attempted unsuccessfully to mount an interior attack of the Haunted Castle. Fire fighters then utilized 2 1/2-inch handlines and master stream appliances to extinguish the fire from the exterior.

Fire fighting operations eventually involved a total of 15 mutual aid fire department units and 300 fire fighters before the fire was declared under control, shortly after 7:45 p.m..

Damage and Casualties

The 17 trailers and the facade which comprised the Haunted Castle facility were destroyed in this fire.

According to the Ocean County Coroners office, eight young adults, who ranged in age from 15 to 19, died as a result of smoke inhalation and carbon monoxide poisoning. Seven of the victims were found in the corridor near the hunchback display and the eighth victim was found in the vicinity of the coffin display (See Figure 1).

IV. ANALYSIS

Investigators from the Ocean County Prosecutors Office, the Ocean County Fire Marshal's office and the New Jersey State Police determined the cause of the fire to be the accidental ignition of polyurethane foam padding on the wall of the strobe room.

According to investigators, on the night of the fire a 14 year-old youth was using a lighter to illuminate his path of travel. Apparently, a very common practice in the Castle was for the visitors to light matches or lighters to illuminate their path of travel. Reportedly, the employees were constantly instructing guests to put out the matches or lighters. The investigators also determined that a strobe-light was malfunctioning on the day of the fire and would not operate for periods of 3 to 4 minutes, leaving the corridor in total darkness. The youth accidentally walked into the foam pad on the strobe room wall, setting it on fire. The youth then attempted to beat it out, but was unsuccessful, and apparently continued through the Castle.

Once ignited, the wall mounted polyurethane foam pad burned rapidly in the vertical plane in the corner of the trailer. Fire spread down the strobe room corridor further fueled by the plywood construction of the ceiling, floor and walls. Once the fire had spread through the corridor, it extended past the phantom of the opera area and to other portions of the Haunted Castle.

Materials identification and small scale fire tests were performed on fire scene samples by the National Bureau of Standards/Center for Fire Research and the Consumer Products Safety Commission. Flexible foam samples were identified as polyurethane, and it was determined that the material did not show any of the elements normally used in flame retardants for foams of this type, suggesting that no such retardants were present. In addition, the foam

was found to readily ignite with a 1-second (approximate) application of a small flame from a butane cigarette lighter. Due to the limited amount of foam available, no heat release testing was possible.

Flame spread tests were conducted on two different plywoods - 1/4-inch and 1/2-inch, using the Radiant Panel Test Method, ASTM E-162.* The 1/4-inch plywood was found to be typical of untreated plywoods with a flame spread index near 200 (Class D). The 1/2-inch plywood sample was typical of fire retardant treated plywoods with a flame spread index near 40 (Class B). Treated plywoods such as these generally contribute little to a fire until near flashover at which time they will burn, but even then, releasing energy substantially slower than untreated plywood.

Investigators determined the victims were traveling through the Haunted Castle in two groups. As the first group of five teenagers made their way through the darkened passages, they passed the hunchback display and then a view of the revolving barrel.** As the five visitors were nearing the phantom of the opera station, they encountered smoke and heat. Investigators believe it was most likely at this point that they started to retreat back through the darkened passageways.

Meanwhile, a second group of four young adults were still advancing through the Haunted Castle and were approaching the revolving barrel display

*This test method is generally recognized for research and development purposes only, and is useful for such research work as fire investigations in that smaller sample sizes can be used. It should be noted that the ASTM E-162 method does not correlate well with NFPA 255 (ASTM E-84) Method of Surface Burning Characteristics of Building Materials which is referenced by such Codes as NFPA 101, the Life Safety Code®.

**Occupants were able to view the barrel from the adjacent passageway.

when they met the first group of teenagers in retreat. All nine visitors then attempted to reverse their path and exit through the main entrance of the Haunted Castle.

Two of the nine visitors were able to retreat as far as the coffin display when they were overcome by smoke and collapsed. A Great Adventure employee was able to rescue one of these two visitors. The other seven victims were found in a corridor near the hunchback display.

A review of employee actions during the early stages of the fire, indicates there was a delay of approximately five minutes between the time the employee working in the Haunted Castle at the butcher display first smelled smoke (approximately 6:30 p.m.) and the time he telephoned the Great Adventure Fire Brigade at 6:35 p.m.. The fire by this point was well established, as the captain of the Fire Brigade reported observing heavy smoke while enroute to the scene. By the time the two Fire Brigade members arrived at the front of the Haunted Castle and one of them advanced a 1 1/2-inch handline through the entrance, the fire was already of such intensity that the captain was only able to progress approximately 20 feet into the structure before being driven back by intense heat.

It was not until 6:41 p.m. that the first mutual aid fire department units from Jackson Township were dispatched. The first of these units did not arrive on the scene until approximately 6:52 p.m., at which point the structure was fully involved in fire.

Code Analysis

The following discussion is presented in the interest of comparing life safety problems observed in this incident to the requirements of the

1981 edition of NFPA 101, Life Safety Code®, (the Code) and the 1984 edition of the BOCA Basic/National Building Code (B/NBC). The areas addressed in this section are not all-inclusive of the code sections that might apply to a structure of this type, but include those areas believed to have the greatest impact on the life safety problems.*

Prior to the performance of a code analysis, the Haunted Castle's use group or type of occupancy under each code has to be determined. Sections 8-1.4.1 and 9-1.4.1 of the Code classify this occupancy as a Class C place of assembly while Section 302.4 of the B/NBC classifies this occupancy as a use group A-3 place of assembly. The requirements discussed below address application of protection features for both new and existing places of assembly as specified in the codes used in the analysis.

1. Means of Egress Lighting. The Code provisions for both new and existing assembly occupancies are the same. Sections 8-2.8 (new) and 9-2.8 (existing) require compliance with Section 5.8 which states, the floors of means of egress shall be illuminated at all points including angles and intersections of passageways and exit doors to values of not less than 1 footcandle measured at the floor. Section 824.0 of the B/NBC also requires that all means of egress be illuminated such that the intensity of floor lighting is not less than 1 footcandle.

2. Emergency Lighting. Code Sections 8-2.9 (new) and 9-2.9 (existing) require compliance with Section 5-9 which states, emergency lighting

*The 1981 edition of the Life Safety Code® and the 1984 edition of BOCA Basic/National Building Code were used for this analysis in order that the conditions at the Great Adventure Park on the date of the fire could be compared to the latest editions of the codes. It is recognized that these code editions were not in effect in Jackson Township during the construction of the Haunted Castle facility. In this jurisdiction the Code was not adopted; however, the 1981 edition of the Basic/National Building Code was in effect at the time of the fire.

facilities shall be arranged to maintain not less than 1 footcandle of illumination throughout the means of egress for a period of 1 1/2 hours in the event of failure of the normal lighting. The B/NBC requires in Section 824.4.1 that means of egress lighting be connected to an emergency electrical system to assure continued illumination for a duration of not less than 1 hour in case of primary power loss.

3. Interior Finish. Code Sections 8-3.3 (new) and 9-3.3 (existing) require means of egress corridors to have a minimum of a Class B interior finish in accordance with Section 6-5. Section 6-5.1.5 defines Class B interior finishes as those with a flame spread of 26-75 and smoke development of 0-450 as determined by NFPA 255, Method of Test of Surface Burning Characteristics of Building Materials. Table 1421.5 of the B/NBC requires means of egress corridors to have a minimum of a Class I interior finish which corresponds to flame spread ratings determined by the ASTM E-84 test. Section 1421.5.3 defines Class I as having a flame spread of 0-25.

4. Exit Marking. Code Sections 8-2.10 (new) and 9-2.10 (existing) require means of egress to have signs in accordance with 5-10 which states that access to exits be marked by readily visible signs in cases where the exit or way to reach it is not immediately visible to the occupants. Section 5-10 further states that every exit sign shall be suitably illuminated and shall be visible in both the normal and emergency lighting mode. Section 823.0 of the B/NBC requires that all required means of egress be indicated with internally illuminated signs reading "EXIT", visible from the exit access and, when necessary, supplemented by directional signs in the exit access indicating the direction and way of egress. Section 823.4 requires all exit signs be illuminated at all times when the building is occupied and be connected to an emergency electrical system.

Life Safety Problems

There is some evidence in this fire that is indicative of special life safety problems related to the darkened, haunted house type of environment. Some of the visitors seemed to initially accept a smokey condition as part of the environment, and one group of youngsters within the structure apparently viewed the actual fire in its incipient stage and remarked how real the illusion seemed... only to comprehend on closer examination that the fire was real. These facts would appear to support the necessity of both early detection and alarm systems in such a facility to (1) establish that an emergency situation exists, and (2) activate emergency lighting to facilitate an orderly evacuation from an otherwise darkened environment.

This facility was designed with a darkened, convoluted series of passageways without a clear line of sight toward exits. This arrangement, typical of this type of amusement facility, may require special considerations in the design, arrangement and marking of exits.

As exemplified by the fire growth and development in this incident, where combustibile interior finishes and contents were used to create passageways and displays, automatic sprinklers could have controlled the fire in the incipient stage allowing time for safe evacuation.

Summary


The ignition scenario, involving the synthetic foam at the point of origin, the combustibility of the interior finishes and contents and the lack of detection and extinguishment of the fire in the incipient stages, contributed to the loss of life in this fire. It is quite possible that even further loss of life could have occurred if both sections of the facility had been in operation at the time of the fire.

Special life safety problems exemplified in this incident may have contributed to the failure of some occupants to safely escape. These problems appear to be related to the haunted house type of environment utilizing a darkened, convoluted series of passageways. The application of code requirements and basic fire protection engineering principles would have greatly reduced the potential for fatalities in this incident.

The following are considered to be major factors contributing to loss of life in this fire:

- The failure to detect and extinguish the fire in its incipient stage by means of fixed fire detection and suppression systems.
- The ignition of synthetic foam material and subsequent fire and smoke spread involving combustible interior finishes and contents.
- The difficulty of escape by occupants due to fire conditions in the haunted house type of environment.

V. APPENDICES



† FATALITIES
 ✖ FIRE ORIGIN

NOTE: DRAWING IS NOT TO SCALE

FIGURE 1




FIGURE 2