



Errata

NFPA 17A

Standard for Wet Chemical Extinguishing Systems

2009 Edition

Reference: 5.3.3

Errata No.: 17A-09-01

The Committee on Dry and Wet Chemical Extinguishing Systems notes the following error in the 2009 edition of NFPA 17A, *Standard for Wet Chemical Extinguishing Systems*.

1. *Revise paragraph 5.3.3 as follows:*

5.3.3 Where fixed automatic fire-extinguishing systems are interconnected or interlocked with the cooking equipment power sources so that if the fire-extinguishing system becomes inoperable due to power failure, all sources of fuel and heat to all cooking appliances serviced by ~~those power sources~~ that hood shall automatically shut off-, and electrical power monitoring shall not be required.

This change corrects the language so that Section 5.3.3 correlates with the NFPA 17A ROP and NFPA 17 as originally intended.

Issue Date: January 23, 2009