



Errata

NFPA 1994

Standard on Protective Ensembles for First Responders to CBRN Terrorism Incidents

2007 Edition

Reference: 7.2.3.5 and 7.3.3.4

Errata No.: 1994-07-02 (Reissued)

The Committee on Hazardous Materials Protective Clothing and Equipment notes the following error in the 2007 edition of NFPA 1994, *Standard on Protective Ensembles for First Responders to CBRN Terrorism Incidents*.

1. In 7.2.3.5, revise the text to read as follows:

7.2.3.5 Class 3 glove materials shall be tested for puncture resistance as specified in Section 8.15, Puncture Resistance Test 1, and shall have a puncture resistance of not less than ~~19 N~~ (2.5 lbf) 9 N (2 lbf).

2. In 7.3.3.4, revise the text to read as follows:

7.3.3.4 Class 4 glove materials shall be tested for puncture resistance as specified in Section 8.15, Puncture Resistance Test 1, and shall have a puncture resistance of not less than ~~19 N~~ (2.5 lbf) 9 N (2 lbf).

Issue Date: February 23, 2007

Reissue Date: November 8, 2007