



Errata

NFPA 30A

Code for Motor Fuel Dispensing Facilities and Repair Garages

2008 Edition

Reference: 12.3.2

Errata No.: 30A-08-2

The Committee on Automotive and Marine Service Stations notes the following error in the 2008 edition of NFPA 30A, *Code for Motor Fuel Dispensing Facilities and Repair Garages*.

12.3.2 Aboveground tanks storing LP-Gas shall be separated from any adjacent property line that is or can be built upon, any public way, and the nearest important building on the same property by not less than the distances given in ~~3.3.2~~ Section 6.2 of NFPA 58, Liquefied Petroleum Gas Code.

Issue Date: January 20, 2009

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/codelist)