

Errata

NFPA 403

Standard for Aircraft Rescue and Fire Fighting Services at Airports 1998 Edition

Reference: Table 3-3.1(b)

Errata No.: 403-98-1

The Committee on Aircraft Rescue and Fire Fighting notes the following error in the 1998 edition of NFPA 403, *Standard for Aircraft Rescue and Fire Fighting Services at Airports*.

1. *The correct metric conversion for Table 3-3.1(b) for Protein Foam Discharge Rates is as follows:*

Protein Foam	
Water	Discharge Rate
L	L/min
685.085	322
1135.50	738
3289.17	1268
6551.84	2176
13531.38	4656
19254.30	6132
25851.55	8138
40196.70	10768
50631.95	13172
63406.32	17411

Issue Date: August 11, 1999