



Errata

NFPA 1971

Standard on Protective Ensembles for Structural Fire Fighting and Proximity Fire Fighting

2007 Edition

Reference: 8.59.7.1

Errata No.: 1971-07-4

The Committee on Structural and Proximity Fire Fighting Protective Clothing and Equipment notes the following errors in the 2007 edition of NFPA 1971, *Standard on Protective Ensembles for Structural Fire Fighting and Proximity Fire Fighting*.

1. Revise 8.59.7.1 to read as follows:

8.59.7.1 The inability to deploy the device in 10 seconds or less, or the inability to drag the mannequin 2.5 m (~~100~~ 8 ft) shall constitute failing performance.

Issue Date: July 20, 2011

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/codelist)

Copyright © 2011 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION