



Errata

NFPA 31

Standard for the Installation of Oil-Burning Equipment

2006 Edition

Reference: Figure A.6.7.3

Errata No.: 31-06-01

The Technical Committee on Liquid Fuel Burning Equipment notes the following correction to the 2006 edition of NFPA 31, *Standard for the Installation of Oil-Burning Equipment*.

1. In Figure A.6.7.3, the NOTE should read as follows:

NOTE. All distances are measured from the nearest point of the air inlet or draft vent terminal.

Issue Date: March 26, 2007