



**Errata**

**NFPA 211**

***Standard for Chimneys, Fireplaces, Vents, and  
Solid Fuel-Burning Appliances***

**2013 Edition**

**Reference: 8.1.5.1**

**Errata No.: 211-13-1**

The Committee on Chimneys, Fireplaces, and Venting Systems for Heat-Producing Appliances notes the following error in the 2013 edition of NFPA 211, *Standard for Chimneys, Fireplaces, Vents, and Solid Fuel-Burning Appliances*.

*1. Revise 8.1.5.1 to read as follows:*

**8.1.5.1** Unlisted metal chimneys shall have clearance from buildings and structures to avoid heating combustible material to a temperature in excess of 90°F (50°C) (~~32°C~~) above ambient and to allow inspection and maintenance operations on the chimney.

**Issue Date:** August 2, 2013

**(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see [www.nfpa.org/codelist](http://www.nfpa.org/codelist))**