



ERRATA

## NFPA 30B

### *Code for the Manufacture and Storage of Aerosol Products*

#### 2015 Edition

**Reference:** Tables 6.4.2.7 (e) through 6.4.2.7(l) Footnote

**Errata No:** 30B-15-1

The Committee on Aerosol Products notes the following error in the 2015 edition of NFPA 30B, *Code for the Manufacture and Storage of Aerosol Products*.

1. *Correct the reference in the footnote of tables 6.4.2.7(e) through (l) to read as follows:*

Note: See 6.34.2.9.1 for in-rack sprinkler design.

Issue Date: October 5, 2015

Reissued: October 8, 2015

**(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see [www.nfpa.org/codelist](http://www.nfpa.org/codelist))**

Copyright © 2015 All Rights Reserved  
NATIONAL FIRE PROTECTION ASSOCIATION