



Errata

NFPA 58

Liquefied Petroleum Gas Code

2017 Edition

Reference: 6.21.4, M.1

Errata No: 58-17-2

The Technical Committee on the Liquefied Petroleum Gas Code notes the following errors in the 2017 edition of NFPA 58, *Liquefied Petroleum Gas Code*.

1. Update the references in 6.21.4 to read as follows:

6.21.4 Security and Protection Against Tampering for Section ~~6.19~~ 6.21 and Section ~~6.25~~ 6.27 Systems.

2. Update the reference in Appendix M.1 to read as follows:

M.1 In accordance with ~~12.4.2.4~~ 12.4.2.5, all containers ...

Issue Date: December 5, 2018

(Note: Electronic products and pamphlet reprints may have this errata incorporated. For current information about the NFPA Codes and Standards, including this errata, please see www.nfpa.org/docinfo)

Copyright © 2018 All Rights Reserved
NATIONAL FIRE PROTECTION ASSOCIATION